YOUR POWDER
YOUR PERFORMANCE

END-USE QUALITY NEEDS

- Flowability
- PSD stability
- Low fines / low coarse tail
- Low contamination
- Traceable batches

THE RIGHT POWDER CHARACTERISTICS ARE THE FOUNDATION OF PRODUCT PERFORMANCE.

Particle Size ▪ Particle Size Distribution
Purity ▪ Reproducibility ▪ Particle Morphology